

Chapter 1		p.
Basics DC		p. 2-13
Basics AC	1-phase & 3-phase analysis	p. 2-13
	P,Q,S + power and Impedance Triangle	p. 2-13
	RLC Circuits + analysis	p. 2-13
	PF, PF Correction	p. 2-13
Delta & Y Configurations	Delta-Y, Y-Y, Delta-Delta, Source+Load	p. 14-24
	Parallell loads	p. 14-24
Wattmeters		p. 24-30
Per Unit	1-phase & 3-phase	p. 31-41
	As it relates to XFMRs, Power Systems, & Faults	p. 31-41
Chapter 2: ELECTROMAGNETIC MACHINES		p.
Transformer Basics	Ideal XFRM, XFMR Theory	p. 43-52
	Load Sharing, Parallel Transformers	p. 53-54
	Non-ideal transformers	p. 55
	Transformer testing (SC and OC)	p. 56-58
Current Transformers	NOTE: Also page 157	p. 59-61
PT's and VT's		p. 61
Reactors		p. 62
3-phase connections		p. 63
Chapter 3: ROTATING MACHINES		p.
Types of Torque		p. 67
Synchronous machines	Features of Stator, Features of Rotor	p. 67
	Approx. Equiv. Circuit, 3-phase Sync. Generator	p. 73-76
	Voltage Regulation of Generator	p. 73-76
	Approx. Equiv. Circuit, 3-phase Sync. Motor	p. 76-81
Induction Machines	Wound Rotor, Squirrel Cage	p. 82
	Approx. Equivl. Circuit	p. 86
Flow of power in a machine	Calculate torque and HP	p. 88
Speed-Torque Characteristics		p. 90
Variable Speed Drives		p. 92
Chapter 4: TRANSMISSION & DISTRIBUTION		p.
Voltage Drop		p. 93
Transmission Line Models	Voltage regulation	p. 94
	Short Transmission Line	p. 94
	Medium Transmission Line	p. 95
	Long Transmission Line	p. 95
	GMD & GMR	p. 95
	Bundled Conductors	p. 96
	Power Flow (P-send Q-send)	p. 96
	Transfer of Power Along lines	p. 96-99
Flow of power from one region to another in a power grid		p. 99-102
Line outage distribution factors		p. 103-105
parallel flows		p. 105
feranti rise		p. 106
benefits of being connected to the power grid		p. 107
voltage control		p. 107-108
line loading (SIL)		p. 108-109
frequency control		p. 109
voltage collapse	list of devices	p. 109-111
Substation Bus Configurations	Main & Transfer bus	p. 112
	Ring Bus	p. 112
	Ring Bus with 2 breakers	p. 113-114
	Breaker & a Half	p. 117-118